DFS-3522 Copy 2 of 4 25 August 1958

The Ramo-Wooldridge Corporation Los Angeles 45, California

Dear Sid:

Reference is made to your proposal CMCC Doc. No. 151X5.1160 for continued engineering services on System 1.

The work proposed by referenced document is desired by Customer No. 3 and it is requested a cost estimate be submitted for costs applicable to Requirement No. 3.

Requirement No. 3 has requested that three of the proposed changes be furnished without further delay to correct unsatisfactory conditions which presently exist. These are:

1. Bow tie antenna bracket

2. System 1 power supply - AN/ARN-6 Radio Compass

3. Locking-type connector for B-Unit Recorder

Format, content, and distribution of service bulletins should be in accordance with the procedures established in our letter to all suppliers, No. 24572 dated 21 February 1958.

Very truly yours.

25X1A		Contracting Officer	
25X1A 25X1A	Distribution: Orig - , Ramo-Wooldrid, - A-101, Section A.4. 3 - Chrono, RI		
25X1A	DPS/DCI :lmw (25-8-58)	DOCUMENTINO Z NO CHANGE IN CLASS. M I DOCUMENTINO IN CLASS. M I DOCUMENT	
	2	SECDET OTCOSE	N. America

Approved For Release 2002/06/13 : CIA-RD 81B00878R000300040041-5

Approved For Release 2002/06/13 : CIA-RDP81B00878R000300040041-5 __ _____

20 August 1958

SUBJECT: Proposed Equipment Modifications and Engineering Service

TO: Contracting Officer

Reference your letter DPS-2142 dated 3 July 1958 which forwarded the contractor's proposal for continued engineering service and equipment modifications. The work which the contractor proposes to do is desired for the FOG program, and you are requested to obtain a breakdown of the estimate for those costs applicable only to Requirement No. 3.

Three of the proposed changes are required without further delay to correct unsatisfactory conditions which presently exist. It is requested that the contractor be authorized to furnish service bulletins and kits as proposed for the following modifications:

- 1. Bow tie antenna bracket
- 2. System 1 power supply AN/ARN-6 Radio Compass3. Locking-type connector for B-Unit Recorder

The contractor should be advised that the format, content, and distribution of these service bulletins should be in accordance with procedures established in your recent letter to all suppliers for service bulletins affecting FOG equipment.

25X1A

Lt. Colonel, USAF

cc: WND

Approved For Release 2002/06/13 P81B00878R000300040041-5

DPS-2142 Copy = of 3 3 July 1958

Dear Sid:

Enclosed is a copy of proposal No. CMCC Doc. No. 15115.1160 for continued engineering service on System 1 for the remainder of 1958.

If you are interested in procuring this type of service for Customer No. 3, we will ask the Contractor for a breakdown by customer.

Sincerely,

Dan

Distribution:

Orig - FOG

2 - A-101, Section I

3 - Chrono, RI

25X1A

DES/DCI | lmw (3/7/58)